

WEST VIRGINIA



20

R E C E I V E D

JUN 05 2017

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)
OFFICE USE ONLY
EPA Region III

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☐Revision ☒ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 15 (Kanawha County)

Address: _____

City: _____

County: _____

Location Within Facility: _____

Building Size (Sq. Ft.): _____

Number of Floors: _____

Age (Yrs): _____

Present Use: _____

Prior Use: _____

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

WV License #: AI008690

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor: _____

WV License #: _____

Schedule:

Asbestos Removal:

Start Date: 03/06/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 03/06/17

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/ Environmental Program Manager



RECLAIM

WVHSEM / FEMA

June 23rd Flood Cleanup Project

Kanawha County, WV - Group 15

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTILE | INSPECTOR | INSPECTION DATE | ANALYST | COMPLETE |
|-------|-------------------------------------|-----------------------|---------------------------|--------------|-----------|---------------------|-----------------|-------------------|----------|
| K-151 | 42 Little Thorofare Rd., Clendenin | UK | Vent Mastic on Roof | 6 LF | Assumed | J. Frazier AI008690 | 2/7/2017 | Taylor B. Metcalf | X |
| K-100 | 14470 Elk River Rd., Clendenin | 38.48948, -81.2778 | Linoleum (back porch) | 15 SF | Assumed | J. Frazier AI008690 | 3/28/2017 | Mikaela Batta | |
| K-101 | 2307 River Haven Road, Clendenin | 38.48575, -81.28401 | Window Glazing (basement) | 30 LF | Assumed | J. Frazier AI008690 | 3/28/2017 | Saithya Painkal | |
| K-107 | 7796 Elk River Rd., Clendenin | 38.4828, -81.36388 | Linoleum (bath) | 10 SF | Assumed | J. Frazier AI008690 | 3/28/2017 | Sarah Talley | |
| K-162 | 5162 Elk River Rd., Elkview | 38.453901, -81.453389 | | | | | | | |
| K-103 | 5532 ELK RIVER ROAD, NORTH, ELKVIEW | 38.46956, -81.40108 | Roof Mastic on vents | 5 SF | Assumed | J. Frazier AI008690 | 4/11/2017 | Shilpa Ladekar | |

WEST VIRGINIA



RECEIVED
JUN 05 2017

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Permittees & Asbestos Programs
and Enforcement Branch (SLC62)

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☒

Revision ☒ (Highlight Changes)

Cancellation ☐

Type of Operation:

Demolition ☒

Ordered Demolition ☐

Renovation ☐

Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 16 (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

Lab: CEI Labs

WV License #: AI008690

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 05/16/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 05/16/17

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Handwritten notes:

Handwritten notes:
Handwritten notes:
Handwritten notes?

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Zip Code: 26555

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032

State: WV

Zip Code: 26330

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



RECLAIM

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 16

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTILE | INSPECTOR | INSPECTION DATE | ANALYST | COMPLETE |
|-------|--|-----------------------|--------------------------|--------------|-----------|---------------------|-----------------|-------------------|----------|
| K-128 | 350 Three Mile Road of Coopers Ck., Charleston | 38.44608, -81.54722 | Gray Linoleum | 150 SF | 25% | J. Frazier AI008690 | 2/7/2017 | Taylor B. Metcalf | |
| K-138 | 2972 Pennsylvania Ave., Charleston | 38.399049, -81.576701 | Vent Mastic on Roof | 5 LF | Assumed | J. Frazier AI008690 | 2/7/2017 | Megan Fisher | X |
| K-160 | 4010 Thorofare Rd., Clendenin | 38.524589, -81.317478 | Roof Mastic around vents | 5 LF | Assumed | J. Frazier AI008690 | 3/28/2017 | Saithya Painkal | |

WEST VIRGINIA



RECEIVED
JUN 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (SLC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: Check No:
Postmark Date: Paid By:
Notification No: Amount: \$

Type of Notification:

Original ☐Revision ☒ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 17 (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

WV License #: AI008690

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 04/12/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 04/12/17

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

RECEIVED
JUN 10 1964

RECEIVED
JUN 10 1964

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Title:

Date of Order: ___/___/___

Date Order to Begin: ___/___/___

(Copy of order must be attached.)

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina, Environmental Program Manager



RECLAIM

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 17

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSOTILE | INSPECTOR | INSPECTION DATE | ANALYST | COMPLETE |
|-------|--------------------------------------|-----------------------|-----------------------------|--------------|------------|---------------------|-----------------|-------------------|----------|
| K-133 | 115 Kelly Ave., Clendenin | 38.481518, -81.364928 | White Window Glazing | 120 LF | 5% | J. Frazier AI008690 | 3/20/2017 | Sarah Talley | |
| | | | 9"x9" Floor Tile (bath) | 20 SF | Assumed | | | | |
| K-146 | 223 Elk River Rd., South, Clendenin | 38.487328, -81.355340 | | | | | | | |
| K-156 | 33 Wier Lane, Elkview | 38.469225, -81.400467 | | | | | | | |
| K-165 | 5532-1/2 Elk River Rd., Falling Rock | 38.469466, -81.401047 | Linoleum (center) | 10 SF | Assumed | J. Frazier AI008690 | 3/20/2017 | Mikaela Batta | |
| K-149 | 101 Hazel Dr., Elkview | 38.501549, -81.343533 | Gray Transite siding | 1500 SF | 15% | J. Frazier AI008690 | 3/20/2017 | Ritika Seal | |
| | | | 9"x9" Floor Tile (RM 1) | 128 SF | Assumed | | | | |
| K-88 | 229 Elk River Rd., South, Clendenin | 38.48686, -81.35597 | Old Wiring (bottom of pile) | 25 LF | Assumed | J. Frazier AI008690 | 3/28/2017 | Greg Ruff | |
| | | | Brown Linoleum | 182 SF | 25% | | | | |
| K-98 | 53 Crickett Rd., Elkview | 38.49647, -81.40087 | Gray Window Glazing | 130 LF | 5% | J. Frazier AI008690 | 3/27/2017 | Megan Fisher | |
| | | | Duct Wrap (basement) | 35 SF | Assumed | | | | |
| K-135 | 13 Yellow Rose Lane, Falling Rock | 38.469544, -81.399939 | Linoleum (bath) | 20 SF | Assumed | J. Frazier AI008690 | 3/27/2017 | Taylor B. Metcalf | |
| K-139 | 535B Youngs Bottom Rd., Elkview | 38.460868, -81.426811 | Linoleum (living room) | 5 SF | Assumed | J. Frazier AI008690 | 3/27/2017 | Taylor B. Metcalf | |

WEST VIRGINIA



RECEIVED
JUN 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:

Check No:

Postmark Date:

Paid By:

Notification No:

Amount: \$

Type of Notification:

Original ☐Revision ☒ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 18 (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

WV License #: AI008690

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 04/12/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 04/12/17

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

0 5 1 2 3 4 5 6 7 8 9
10 11 12 13 14 15 16 17 18 19

RECEIVED
JAN 10 1964
U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D.C. 20535

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Zip Code: 26555

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032

State: WV

Zip Code: 26330

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina / Environmental Program Manager



RECLAIM

WVHSEM / FEMA

June 23rd Flood Cleanup Project

Kanawha County, WV - Group 18

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTILE | INSPECTOR | INSPECTION DATE | ANALYST | COMPLETE |
|-------|---|------------------------|------------------------|--------------|-----------|---------------------|-----------------|--------------|----------|
| K-152 | 358 Youngstown Dr., Clendenin | 38.473428, -81.387324 | None Detected | N/A | N/A | J. Frazier AI008690 | 3/20/2017 | Sarah Talley | |
| K-177 | 1222 Left Fork Leatherwood Rd., Clendenin | 38.4691221, -81.356815 | Silver Roof Paint | 800 SF | 5% | J. Frazier AI008690 | 3/20/2017 | Sarah Talley | |
| K-203 | 4221 Leatherwood Rd., Clendenin | 38.459090, -81.361057 | Black Tar (porch roof) | 300 SF | 2% | J. Frazier AI008690 | 4/21/2017 | Ritika Seal | |
| | | | Roof Vent Mastic | 50 SF | Assumed | | | | |

WEST VIRGINIA



RECEIVED
JUN 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (SLC62)
EPA Region IV

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:

Check No:

Postmark Date:

Paid By:

Notification No:

Amount: \$

Type of Notification:

Original ☐Revision ☒ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 19 (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

WV License #: AI008690

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 04/12/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 04/12/17

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/ Environmental Program Manager



RECLAIM

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 19

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTILE | INSPECTOR | INSPECTION DATE | ANALYST | COMPLETE |
|-------|--------------------------------|-----------------------|-----------------------------|--------------|-----------|---------------------|-----------------|---------------|----------|
| K-147 | 406 Kanawha Ave., Clendenin | 38.489652, -81.340114 | Linoleum (bath) | 25 SF | Assumed | J. Frazier AI008690 | 3/20/2017 | Sarah Talley | |
| K-159 | 744 Maywood Ave., Clendenin | 38.481878, -81.361603 | Chimney Mastic | 5 SF | Assumed | J. Frazier AI008690 | 3/20/2017 | Mikaela Batta | |
| K-174 | 1964 Jordan Creek Rd., Elkview | 38.482234, -81.390133 | | | | | | | |
| K-199 | 311 Brown Street, Clendenin | 38.477640, -81.369491 | Old Wire (back top of pile) | 25 LF | Assumed | J. Frazier AI008690 | 4/23/2017 | Samantha Card | |

WEST VIRGINIA



R E C E I V E D
JUN 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (SLC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:

Check No:

Postmark Date:

Paid By:

Notification No:

Amount: \$

Type of Notification:

Original ☐**Revision** ☒ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 20 (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

WV License #: AI008690

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 04/12/17

Completion Date 08/04/17

Demo/Renovation:

Start Date: 04/12/17

Completion Date 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

FOR RELEASE BY
THE DIRECTOR, FBI (100-442811)
DATE 10-10-68 BY SP-5 JCL/ML

NOV 10 1968

100-442811-1000

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina / Environmental Program Manager



RECLAIM

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 20

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTILE | INSPECTOR | INSPECTION DATE | ANALYST | COMPLETE |
|-------|------------------------------------|-----------------------|---------------------------------|--------------|-----------|---------------------|-----------------|--------------|----------|
| K-153 | 241 Pleasant Lane, Clendenin | 38.512916, -81.355289 | White Window Glazing | 100 LF | 5% | J. Frazier AI008690 | 3/20/2017 | Sarah Talley | |
| | | | Chimney Mastic | 5 SF | Assumed | | | | |
| K-157 | 2792 Pennsylvania Ave., Charleston | 38.394538, -81.586673 | 9"x9" Floor Tile (under carpet) | 250 SF | Assumed | J. Frazier AI008690 | 3/20/2017 | Sarah Talley | |
| K-132 | 39 Mink Lane, Charleston | 38.39954, -81.57619 | Linoleum (bath) | UK | Assumed | J. Frazier AI008690 | 3/27/2017 | Megan Fisher | |

WEST VIRGINIA



RECEIVED
JUN 05 2017

Pesticides & Asbestos Programs
and Environmental Branch (SLC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☒Revision ☐ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 7 (Greenbrier)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Please see attached.

WV License #: Please see attached.

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 05/31/2017

Completion Date: 08/04/2017

Demo/Renovation:

Start Date: 05/31/2017

Completion Date: 08/04/2017

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 5 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina Environmental Program Manager



RECLAIM

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 7

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTOTILE | INSPECTION DATE | INSPECTOR | ANALYST | COMPLETE |
|-------|--|-----------------------|---------------------------------|--------------|-------------|-----------------|------------------------|----------------|----------|
| G-86 | 344 FREELAND AVE., WHITE SULPHUR SPRINGS | 37.801529, -80.290507 | Mastic around roof vent | 5 SF | Assumed | 2/1/2017 | K. Tuckwiller AI008994 | Sarah Talley | X |
| G-110 | 218 CRESCENT AVE., WHITE SULPHUR SPRINGS | 37.797183, -80.299736 | No Suspect Material | N/A | N/A | 2/1/2017 | K. Tuckwiller AI008994 | N/A | X |
| G-121 | 207 FREELAND AVE., WHITE SULPHUR SPRINGS | 37.801944, -80.290418 | Silver Roof Cement | 1000 SF | 5% | 2/1/2017 | K. Tuckwiller AI008994 | Sarah Talley | X |
| | | | Black Mastic around Roof Vents | 5 SF | Assumed | | | | X |
| G-184 | 236 FREELAND AVE., WHITE SULPHUR SPRINGS | 37.802467, -80.290398 | Silver Roof Cement | 800 SF | 3% | 2/14/2017 | K. Tuckwiller AI008994 | Shilpa Ladekar | X |
| | | | Mastic around roof vent | 5 SF | Assumed | | | | X |
| G-185 | 221 FREELAND AVE., WHITE SULPHUR SPRINGS | 37.802130, -80.290712 | Mastic on Roof/Siding | 20 SF | Assumed | 2/14/2017 | K. Tuckwiller AI008994 | Greg Ruff | X |
| G-195 | 204 FREELAND AVE., WHITE SULPHUR SPRINGS | 37.802015, -80.290050 | Mastic around roof vent | 5 SF | Assumed | 2/14/2017 | K. Tuckwiller AI008994 | Shilpa Ladekar | X |
| G-106 | 183 WEBB ST., WHITE SULPHUR SPRINGS | 37.803820, -80.297286 | DEBRIS PILE ALREADY REMOVED | N/A | N/A | 2/15/2017 | N/A | N/A | X |
| G-108 | 197 IVY ST., WHITE SULPHUR SPRINGS | 37.802246, -80.300145 | Gray Floor Tile | 20 SF | 3% | 2/14/2017 | K. Tuckwiller AI008994 | Megan Rumble | X |
| | | | Tar Paper | 30 SF | Assumed | | | | X |
| G-134 | 127 VANSTAVERN LANE, WHITE SULPHUR SPRINGS | 37.835539, -80.256784 | Mastic around Roof Vents | 4 SF | Assumed | 2/1/2017 | K. Tuckwiller AI008994 | Sarah Talley | X |
| G-146 | 466 BIG DRAFT ROAD, WHITE SULPHUR SPRINGS | 37.798877, -80.301825 | Silver/Black Roof Cement/Mastic | 300 SF | 10% | 2/1/2017 | K. Tuckwiller AI008994 | Sarah Talley | X |
| | | | Window Glazing | 20 LF | Assumed | | | | X |
| G-187 | 116 VAN STAVERN LANE, WHITE SULPHUR SPRINGS | 37.835281, -80.257131 | No Suspect Material | N/A | N/A | 2/14/2017 | K. Tuckwiller AI008994 | N/A | X |
| G-190 | 342 FREELAND AVE., WHITE SULPHUR SPRINGS | 37.802521, -80.290881 | Silver Roof Paint | 1000 SF | Assumed | 2/14/2017 | K. Tuckwiller AI008994 | N/A | X |
| G-104 | 158 CRAWFORD LANE, WHITE SULPHUR SPRINGS | 37.791083, -80.306297 | Silver Roof Cement | 1200 SF | Assumed | 2/14/2017 | K. Tuckwiller AI008994 | Greg Ruff | X |
| | | | Roof Shingles (Bldg 1) | 500 SF | Assumed | | | | X |
| G-194 | 206 SWAN LANE, WHITE SULPHUR SPRINGS | 37.792272, -80.304619 | No Suspect Material | N/A | N/A | 2/14/2017 | K. Tuckwiller AI008994 | N/A | X |
| G-113 | 255 DRY CREEK RD., WHITE SULPHUR SPRINGS | 37.793554, -80.298316 | Gray/Tan Window Glazing | 120 LF | 3% | 5/23/2017 | K. Tuckwiller AI008994 | Scott Minyard | |
| | | | Transite Siding | 500 SF | Assumed | | | | |
| | | | Window Glazing (Bldg 1) | 20 LF | Assumed | | | | |
| G-189 | 256 MILL HILL DR., WHITE SULPHUR SPRINGS | 37.798863, -80.300035 | Window Glazing (Bldg 2) | 14 LF | Assumed | 5/23/2017 | K. Tuckwiller AI008994 | Ritika Seal | |
| | | | Linoleum #4 (Tan Linoleum) | 22 SF | 25% | | | | |
| | | | Linoleum #5 (Gloset) | 45 SF | Assumed | | | | |
| G-216 | 43521 MIDLAND TRL., E., WHITE SULPHUR SPRINGS | 37.794730, -80.275334 | Transite Siding | 360 SF | Assumed | 5/23/2017 | K. Tuckwiller AI008994 | Scott Minyard | |
| | | | Transite Siding (Bldg 1) | 80 SF | Assumed | | | | |
| G-286 | 325 FREELAND AVE., WHITE SULPHUR SPRINGS | 37.801854, -80.290697 | Silver Paint (roof) | 900 SF | 3% | 5/23/2017 | K. Tuckwiller AI008994 | Mikaela Batta | |
| G-298 | 184 (135) FREELAND AVE., WHITE SULPHUR SPRINGS | 37.801863, -80.289954 | Mastic around roof vents | 4 SF | Assumed | 5/23/2017 | K. Tuckwiller AI008994 | Ritika Seal | |

WEST VIRGINIA



RECEIVED
JUN 05 2017

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Pesticides & Asbestos Programs
and Environmental Programs (PLC62)
EPA Region III

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☒

Revision ☐ (Highlight Changes)

Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐

Renovation ☐

Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 9 (Greenbrier)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Please see attached.

WV License #: Please see attached.

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 05/31/2017

Completion Date: 08/04/2017

Demo/Renovation:

Start Date: 05/31/2017

Completion Date: 08/04/2017

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

SECRET
TOP SECRET

CONFIDENTIAL
TOP SECRET

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM/PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 5/31/17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



RECLAIM3

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 9

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTOLE | INSPECTION DATE | INSPECTOR | ANALYST | COMPLETE |
|-------|----------------------------------|-----------------------|-------------------------------------|--------------|-----------|-----------------|------------------------|----------------|----------|
| G-73 | 6256 MIDLAND TRIL. WEST, CHARMCO | 37.988079, -80.730745 | Silver Roof Cement | 1200 SF | 2% | 2/6/2017 | K. Tuckwiller AI008994 | Samantha Card | X |
| | | | Mastic around roof cents/chimney | 5 SF | Assumed | | | | X |
| G-120 | 402 LEWIS ST., RUPERT | 37.961479, -80.694279 | Mastic on Roof | 40 SF | Assumed | 2/15/2017 | J. Sommers AI008854 | Daniel Liguori | X |
| G-131 | 247 FEAMSTER RD., RUPERT | 37.959103, -80.681364 | Black Mastic on 1st layer roof | 100 SF | Assumed | 2/6/2017 | K. Tuckwiller AI008994 | Mikaela Batta | X |
| G-114 | 295 FEAMSTER RD., RUPERT | 37.958985, -80.680680 | Roof Mastic | 5 SF | Assumed | 2/15/2017 | J. Sommers AI008854 | Daniel Liguori | X |
| | | | Roof Shingles (Bldg 1) | 20 SF | Assumed | | | | X |
| G-122 | 210 MAPLE DR., RAINELLE | 37.952261, -80.685492 | Black Mastic around conduit on roof | 2 SF | Assumed | 2/6/2017 | K. Tuckwiller AI008994 | Sarah Talley | |

WEST VIRGINIA



RECEIVED
JUN 05 2017

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Pesticides & Asbestos Programs
and Environmental Branch (SLC62)
EPA Region III

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:

Check No:

Postmark Date:

Paid By:

Notification No:

Amount: \$

Type of Notification:

Original ☐**Revision** ☒ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 12 (Greenbrier)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Please see attached.

WV License #: Please see attached.

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 03/28/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 03/28/17

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

30 30 30 30 30

YMS CO. 1911

Copyright 1911 by YMS CO.
All rights reserved.
Printed in U.S.A.

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

| | | |
|--------|---------|-------------|
| Pipes: | Ln. Ft: | % Asbestos: |
| Area: | Sq. Ft: | % Asbestos: |
| Other: | Cu. Ft: | % Asbestos: |

Type(s):

| | | |
|--------|---------|-------------|
| Pipes: | Ln. Ft: | % Asbestos: |
| Area: | Sq. Ft: | % Asbestos: |
| Other: | Cu. Ft: | % Asbestos: |

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Phone: 304-366-7070

Zip Code: 26555

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032


State: WV

Phone: 304-842-2784

Zip Code: 26330

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 12

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSHOTILE | INSPECTION DATE | INSPECTOR | ANALYST | COMPLETE |
|-------|--------------------------------------|-----------------------|---|--------------|-------------|-----------------|------------------------|-------------------|----------|
| G-132 | 101 2ND STREET, CHARMCO | 38.002327, -80.738625 | Mastic on roof | 5 LF | Assumed | 3/21/2017 | K. Tuckwiller AI008994 | Samantha Card | X |
| G-85 | 293 RALEIGH STREET, RUPERT | 37.96262, -80.684022 | Mastic around chimney | 8 SF | Assumed | 3/21/2017 | K. Tuckwiller AI008994 | Saithya Painkal | X |
| G-129 | 401 3RD STREET, SOUTH, RUPERT | 37.962274, -80.696227 | Cream/Patterned Linoleum | 15 SF | 25% | 3/21/2017 | K. Tuckwiller AI008994 | Shilpa Ladekar | X |
| G-138 | 168 F STREET, RUPERT | 37.968489, -80.678315 | Roof Vent Mastic | 8 SF | Assumed | 3/21/2017 | K. Tuckwiller AI008994 | Mikaela Batta | X |
| G-127 | 1026 ANJEAN ROAD, RUPERT | 37.971808, -80.675783 | Mastic on chimney | 5 LF | Assumed | 3/21/2017 | K. Tuckwiller AI008994 | Mikaela Batta | X |
| G-255 | 1158 ANJEAN ROAD, RUPERT | 37.973448, -80.674812 | Chimney Mastic | 5 SF | Assumed | 3/21/2017 | K. Tuckwiller AI008994 | N/A | X |
| G-128 | 288 TOMMY HALL ROAD, RUPERT | 37.951092, -80.685285 | Black Mastic on Metal Siding | 30 SF | Assumed | 3/21/2017 | K. Tuckwiller AI008994 | Taylor B. Metcalf | X |
| G-204 | 1476 ANJEAN ROAD, RUPERT | 37.977630, -80.672558 | Mastic around roof vents | 10 SF | Assumed | 3/31/2017 | K. Tuckwiller AI008994 | N/A | |
| G-227 | 252 ANTHONY LANE, RUPERT | 37.977290, -80.669866 | Black Roof Cement/Mastic | 10 SF | Assumed | 3/30/2017 | K. Tuckwiller AI008994 | Taylor B. Metcalf | |
| | | | Brown/Tan Linoleum | 10 SF | 25% | | | | |
| | | | Silver Roof Cement | 20 SF | Assumed | 3/30/2017 | K. Tuckwiller AI008994 | Taylor B. Metcalf | |
| | | | Old Roof Shingles (Bldg 3) | 180 SF | Assumed | | | | |
| G-228 | 254 ANTHONY LANE, RUPERT | 37.977154, 80.669919 | Silver Roof Cement (Bldg 3) | 300 SF | 2% | 3/30/2017 | K. Tuckwiller AI008994 | Daniel Liguori | |
| | | | Mastic around chimney (Main) | 5 SF | Assumed | | | | |
| | | | Old Shingles (Bldg 1) | 60 SF | Assumed | | | | |
| | | | Black Mastic/Cement (Bldg 2) | 10 SF | Assumed | | | | |
| G-259 | 201 MAPLE DRIVE, RUPERT | 37.951901, 80.685670 | Mastic on roof/chimney (main) | 7 SF | Assumed | 3/31/2017 | K. Tuckwiller AI008994 | Mikaela Batta | |
| G-226 | 217 SINKING CREEK ROAD, CLINTONVILLE | 37.897707, -80.540286 | Roof Shingles (Bldg 1) | 110 SF | Assumed | 3/31/2017 | K. Tuckwiller AI008994 | Taylor B. Metcalf | |
| | | | Silver Roof Cement | 10 SF | Assumed | | | | |
| G-133 | 124 2ND STREET, CHARMCO | 38.002261, -80.737987 | Mastic around roof vent | 2 SF | Assumed | 3/30/2017 | K. Tuckwiller AI008994 | Scott Minyard | |
| | | | Roof Shingles (Bldg 1) | 110 SF | Assumed | | | | |
| | | | Roof Shingles (Bldg 2) | 320 SF | Assumed | | | | |
| G-148 | 4566 MIDLAND TRL, WEST, CHARMCO | 38.004857, -80.746844 | Black Tar | 300 SF | 2% | 3/30/2017 | K. Tuckwiller AI008994 | Megan Rumble | |
| | | | Transite Siding | 500 SF | Assumed | | | | |
| G-149 | 5292 MIDLAND TRL, WEST, CHARMCO | 38.000757, -80.736831 | 4x8 Asbestos Panels | 1300 SF | Assumed | 3/30/2017 | K. Tuckwiller AI008994 | Scott Minyard | |
| | | | Mastic/Cement on Flashing | 15 SF | Assumed | | | | |
| G-196 | 125 2ND STREET, CHARMCO | 38.002433, -80.738250 | Black Surface Tar | 200 SF | 5% | 3/30/2017 | K. Tuckwiller AI008994 | Scott Minyard | |
| | | | Black Mastic (between siding/porch) | 15 SF | Assumed | | | | |
| G-229 | 6964 MIDLAND TRL, WEST, CHARMCO | 37.983628, -80.719168 | Mastic around electrical conduit (Bldg 1) | 1 SF | Assumed | 3/30/2017 | K. Tuckwiller AI008994 | Scott Minyard | |
| | | | Old Shingles/Mastic | 20 SF | Assumed | | | | |
| G-262 | 5162 MIDLAND TRL, WEST, CHARMCO | 38.002235, -80.737581 | White Window Glazing | 120 LF | 3% | 3/30/2017 | K. Tuckwiller AI008994 | Taylor B. Metcalf | |
| | | | Mastic around Chimney | 3 SF | Assumed | | | | |
| | | | Black Mastic on Roof (Bldg 1) | 6 SF | Assumed | | | | |
| | | | Black Mastic (Bldg 2) | 10 SF | Assumed | | | | |
| G-258 | 6702 MIDLAND TRL, WEST, HINES | 37.985379, -80.723363 | Silver/White Roof Cement | 700 SF | 10% | 3/30/2017 | K. Tuckwiller AI008994 | Greg Ruff | |
| | | | Mastic on Roof | 10 SF | Assumed | | | | |
| G-266 | 1175 ANJEAN ROAD, RUPERT | 37.973955, -80.675135 | Window Glazing | 100 LF | Assumed | 4/4/2017 | K. Tuckwiller AI008994 | Saithya Painkal | |
| G-219 | 268 MAPLE DR, RUPERT | 37.952767, -80.686318 | Gray/Brown/Floor Tile | 18 SF | 2% | 5/19/2017 | K. Tuckwiller AI008994 | Greg Ruff | |
| | | | Mastic around chimney | 2 SF | Assumed | | | | |
| G-220 | 1412 ANJEAN RD, RAINELLE | 37.976759, -80.673044 | Old Window Siding | 80 LF | Assumed | 5/19/2017 | K. Tuckwiller AI008994 | Samantha Card | |
| | | | Linoleum (Bldg 1) | 25 SF | Assumed | | | | |
| G-224 | 534 TOMMY HALL RD, RUPERT | 37.950966, -80.684448 | Old Linoleum (Yellow) | 12 SF | Assumed | 5/19/2017 | K. Tuckwiller AI008994 | Shilpa Ladekar | |
| | | | Cream Window Glazing | 80 LF | 2% | 5/19/2017 | K. Tuckwiller AI008994 | Shilpa Ladekar | |
| G-230 | 144 ROBINSON ROAD, RUPERT | 37.971647, -80.674986 | Mastic around chimney | 8 SF | Assumed | 5/19/2017 | K. Tuckwiller AI008994 | Shilpa Ladekar | |
| | | | Tar Paper (Bldg 2) | 15 SF | Assumed | | | | |
| G-244 | 6718 MIDLAND TRL, WEST, HINES | 37.985173, -80.723084 | Mastic around conduit on roof | 1 SF | Assumed | 5/18/2017 | K. Tuckwiller AI008994 | Ritika Seal | |
| G-287 | 208 F ST, RUPERT | 37.969132, -80.676540 | Black Mastic (roof vent) | 1 SF | Assumed | 5/19/2017 | K. Tuckwiller AI008994 | Scott Minyard | |

WEST VIRGINIA



RECEIVED
JUN 05 2017

Pesticides & Asbestos Programs
Enforcement Branch (SLC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☐~~Revision~~ ☒ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 14 (Greenbrier)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Please see attached.

WV License #: Please see attached.

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 04/03/17

~~Completion Date:~~ 08/04/17

Demo/Renovation:

Start Date: 04/03/17

~~Completion Date:~~ 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

RECEIVED
JUN 10 2011

Product & Application
and Environmental Health
EPA Region 10

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Phone: 304-366-7070

Zip Code: 26555

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032


State: WV

Phone: 304-842-2784

Zip Code: 26330

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



RECLAIM3

WVHSEM / FEMA

June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 14

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSOTILE | INSPECTION DATE | INSPECTOR | ANALYST | COMPLETE |
|-------|--|-----------------------|--|--------------|------------|-----------------|------------------------|-------------------|----------|
| G-252 | 231 HONAKER HOLLOW RD., CALDWELL | 37.766931, -80.392479 | Black Mastic on Roof | 10 SF | Assumed | 3/23/2017 | K. Tuckwiller AI008994 | Samantha Card | X |
| G-239 | 696 TUCKAHOE RD., WHITE SULPHUR SPRINGS | 37.790345, -80.290943 | NO SUSPECT MATERIALS | N/A | N/A | 3/23/2017 | K. Tuckwiller AI008994 | N/A | |
| G-245 | 187 GEORGEANNA DR., WHITE SULPHUR SPRINGS | 37.915892, -80.209482 | NO SUSPECT MATERIALS | N/A | N/A | 3/23/2017 | K. Tuckwiller AI008994 | N/A | |
| G-109 | 202 WEBB ST., WHITE SULPHUR SPRINGS | 37.803603, -80.29755 | Mastic on Roof Vent/Chimney | 3 SF | Assumed | 3/23/2017 | K. Tuckwiller AI008994 | Taylor B. Metcalf | |
| G-111 | 219 CRESCENT AVENUE, WHITE SULPHUR SPRINGS | 37.797888, -80.300358 | Transite Siding | 300 SF | Assumed | 3/23/2017 | K. Tuckwiller AI008994 | Samantha Card | X |
| G-257 | 238 4TH STREET, CALDWELL | 37.779346, -80.391948 | Mastic around Roof vents (under metal roofing) | 5 SF | Assumed | 3/28/2017 | K. Tuckwiller AI008994 | Saithya Painkal | X |
| G-103 | 154 2ND STREET, CALDWELL | 37.779713, -80.392247 | White/Gray Window Glazing | 180 LF | 2% | 3/27/2017 | K. Tuckwiller AI008994 | 149% | X |
| | | | Mastic around chimney | 4 SF | Assumed | | | | X |
| G-205 | 3961 MONROE DRAFT ROAD, CALDWELL | 37.755756, -80.403356 | NO SUSPECT MATERIALS | N/A | N/A | 3/27/2017 | K. Tuckwiller AI008994 | N/A | |
| G-211 | 650 HEARTS RUN LOOP ROAD, CALDWELL | 37.765986, -80.357265 | NO SUSPECT MATERIALS | N/A | N/A | 3/27/2017 | K. Tuckwiller AI008994 | N/A | |
| G-112 | 246 SALISBURY AVENUE, WHITE SULPHUR SPRINGS | 37.791595, -80.304954 | Brown/White Linoleum | 350 SF | 25% | 3/27/2017 | K. Tuckwiller AI008994 | Samantha Card | |
| | | | Mastic around roof vents | 5 SF | Assumed | | | | |
| | | | Roofing Material (Bldg 1) | 110 SF | Assumed | | | | |
| G-171 | 530 BIG DRAFT ROAD, WHITE SULPHUR SPRINGS | 37.799785, -80.301775 | Window Glazing | 80 LF | Assumed | 3/27/2017 | K. Tuckwiller AI008994 | Shilpa Ladekar | |
| G-178 | 126 VAN STAVERN LANE, WHITE SULPHUR SPRINGS | 37.835262, -80.256981 | Silver Roof Cement | 700 SF | 2% | 3/27/2017 | K. Tuckwiller AI008994 | Samantha Card | |
| | | | Mastic on Siding/Roof Vents | 10 SF | Assumed | | | | |
| G-179 | 241 FREELAND AVENUE, WHITE SULPHUR SPRINGS | 37.802313, -80.290882 | Gray/Black Silver Roof Cement | 500 SF | 2% | 3/27/2017 | K. Tuckwiller AI008994 | Saithya Painkal | |
| | | | Mastic around roof vents | 5 SF | Assumed | | | | |
| | | | Black Roof Tar | 500 SF | 10% | | | | |
| G-231 | 43117 MIDLAND TRAIL, EAST, WHITE SULPHUR SPRINGS | 37.798882, -80.279446 | Silver Roof Cement | 150 SF | Assumed | 3/27/2017 | K. Tuckwiller AI008994 | Sarah Talley | |
| | | | Caulking around windows (Bldg 1) | 20 LF | Assumed | | | | |
| G-233 | 208 FREELAND AVENUE, WHITE SULPHUR SPRINGS | 37.802245, -80.290287 | Mastic on Roof Vents/Siding | 10 SF | Assumed | 3/27/2017 | K. Tuckwiller AI008994 | Scott Minyard | |
| G-261 | 160 MOUNTAINEER LANE, WHITE SULPHUR SPRINGS | 37.795663, -80.275982 | NO SUSPECT MATERIALS | N/A | N/A | 3/28/2017 | K. Tuckwiller AI008994 | N/A | |
| G-263 | 228 HOLMES LANE, WHITE SULPHUR SPRINGS | 37.794948, -80.296896 | Black Roof Cement | 15 SF | Assumed | 4/4/2017 | K. Tuckwiller AI008994 | N/A | |
| G-198 | 162 1st STREET, CALDWELL | 37.779797, -80.393328 | Mastic around roof vents | 5 SF | Assumed | 4/24/2017 | K. Tuckwiller AI008994 | Megan Rumble | |
| G-169 | 154 TUNNEL LOOP ROAD, CALDWELL | 37.776857, -80.393704 | Transite Siding | 4000 SF | Assumed | 4/24/2017 | K. Tuckwiller AI008994 | Megan Rumble | |
| G-289 | 43220-A MIDLAND TRAIL, EAST, WHITE SULPHUR SPRINGS | 37.797610, -80.278891 | Mastic around roof vents | 3 SF | Assumed | 4/24/2017 | K. Tuckwiller AI008994 | Megan Rumble | |
| G-107 | 190 MILL HILL DRIVE, WHITE SULPHUR SPRINGS | 37.797545, -80.298423 | Red Floor Tile | 190 SF | 3% | 4/24/2017 | K. Tuckwiller AI008994 | Scott Minyard | |
| | | | Transite Siding | 1400 SF | Assumed | | | | |
| G-168 | 142 TUNNEL LOOP ROAD, CALDWELL | 37.776693, -80.393704 | Yellow Linoleum | 120 SF | 25% | 4/24/2017 | K. Tuckwiller AI008994 | Mikaela Batta | |
| | | | Transite Siding | 3600 SF | Assumed | | | | |
| G-206 | 5264 MONROE DRAFT RD., CALDWELL | 37.771840, -80.392749 | Mastic/Roof Cement around chimney & at joining back addition | 15 SF | Assumed | 5/23/2017 | K. Tuckwiller AI008994 | Ritika Seal | |
| G-214 | 36288 MIDLAND TRL., EAST, CALDWELL | 37.776201, -80.383344 | Transite Siding | 1000 SF | Assumed | 5/23/2017 | K. Tuckwiller AI008994 | Scott Minyard | |
| G-215 | 36479 MIDLAND TRL., EAST, CALDWELL | 37.774053, -80.380656 | Mastic around chimneys | 5 SF | Assumed | 5/23/2017 | K. Tuckwiller AI008994 | Ritika Seal | |
| | | | Roof Shingles (Bldg 1) | 60 SF | Assumed | | | | |

WEST VIRGINIA



RECEIVED
JUN 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (SLC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☒Revision ☐ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 1 (Nicholas County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Please see attached.

WV License #: Please see attached.

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Christopher Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 05/31/2017

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 05/31/2017

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

WAX - 1000

[illegible]

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Title:

Date of Order: ___/___/___

Date Order to Begin: ___/___/___

(Copy of order must be attached.)

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV


Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



RECLAIM3

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Nicholas County, WV - Group 1

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSOPILE | INSPECTION DATE | INSPECTOR | ANALYST |
|------|--|-----------------------|--------------------------------|--------------|------------|-----------------|-------------|------------------|
| N-14 | 151 N. Fork Cherry Rd., Richwood | 38.237040, -80.530101 | linoleum kitchen | Unknown | Assumed | 12/18/2016 | JS A1008854 | Ryan Williams |
| N-10 | 33 Park Place, Richwood | 38.230348, -80.527065 | window glazing | 160LF | 3% | 12/18/2016 | JS A1008854 | Sarah Talley |
| | | | Mastic on roof vents | 6LF | Assumed | | JS A1008854 | Sarah Talley |
| | | | building 1 b-1 mastic | Unknown | Assumed | | JS A1008854 | Sarah Talley |
| | | | Building 2-b2 roof shingles | Unknown | Assumed | | JS A1008854 | Sarah Talley |
| N-11 | 38 Spruce Street, Richwood | 38.234883, -80.530307 | Tar/Brown caulking | 160LF | 3% | 12/18/2016 | JS A1008854 | Scott Minyard |
| | | | Silver Black tar | 1200SF | 3% | | | |
| | | | Mastic/Flashing on roof | 10LF | Assumed | | | |
| N-12 | 55 Weber Street, Richwood | 38.233237, -80.530387 | linoleum entry | 35sf | 25% | 12/18/2016 | JS A1008854 | Ryan Williams |
| | | | Window Glazing | 104LF | 3% | | JS A1008854 | Ryan Williams |
| | | | 9x9 tile w mastic | 200sf | 3% | | JS A1008854 | Ryan Williams |
| | | | textured ceiling | 330sf | 3% | | JS A1008854 | Ryan Williams |
| | | | mastic on chimney | 8LF | Assumed | | JS A1008854 | Ryan Williams |
| | | | Brown Mastic | 70sf | 3% | | JS A1008854 | Greg Ruff |
| N-42 | 8 W. Walnut Street, Richwood | UK | Electrical | Unknown | Assumed | 12/18/2016 | JS A1008854 | Greg Ruff |
| | | | linoleum in kitchen | 425sf | Assumed | 12/18/2016 | JS A1008854 | Greg Ruff |
| | | | Cupboard | unknown | Assumed | 12/18/2016 | JS A1008854 | Greg Ruff |
| | | | | | | | | |
| N-8 | 18 Oakford Avenue, Richwood | 38.225246, -80.533385 | Red floor tile and mastic | 140SF | 3% | 12/18/2016 | JS A1008854 | Ryan Williams |
| | | | Green floor tile and mastic | 140SF | 3% | | | |
| | | | old wiring | Unknown | Assumed | | | |
| N-2 | 3 Dyer Avenue, Richwood | 38.223025, -80.527806 | window glazing | 138 | 3% | 12/18/2016 | JS A1008854 | Taylor B Metcalf |
| | | | window glazing in entry | 9LF | 2% | | | |
| | | | bottom layer of shingle tar | 1200sf | 10% | | | |
| | | | Building 3 roof shingles | 300sf | Assumed | | | |
| N-6 | 10 Dyer Avenue, Richwood | 38.222936, -80.526850 | caulking around ext vent | 3sf | 5% | 12/21/2016 | JS A1008854 | Ryan Williams |
| | | | old wiring | Unknown | assumed | | | |
| N-3 | 3 Elizabeth Street, Richwood | 38.223231, -80.526980 | Off-white, gray caking plaster | 1700SF | 2% | 12/21/2016 | JS A1008854 | Scott Minyard |
| | | | white-green textured ceiling | 500SF | 2% | | | |
| | | | Off-white, gray plaster | 3500SF | 2% | | | |
| | | | Old Wiring | Unknown | Assumed | | | |
| N-1 | 1 Elizabeth Street, Richwood | 38.223279, -80.527188 | Old Wiring | Unknown | Assumed | 12/21/2016 | JS A1008854 | Taylor B Metcalf |
| N4 | 5 Ellen St, Richwood | 38.223943, -80.526320 | Off-white, blue linoleum | 30sf | 25% | 12/21/2016 | JS A1008854 | Ryan Williams |
| | | | White ceiling material | 320sf | 3% | 12/21/2016 | JS A1008854 | Ryan Williams |
| | | | Roof vent mastic | 3sf | Assumed | 12/21/2016 | JS A1008854 | Ryan Williams |
| | | | building 1 black caulking | 16LF | Assumed | 12/21/2016 | JS A1008854 | Ryan Williams |
| N-5 | 9 McCarty Street, Richwood | 38.217649, -80.521493 | Electrical Tube | 3LF | Assumed | 12/21/2016 | JS A1008854 | Candace Burrus |
| | | | Window Glazing | 8LF | Assumed | 12/21/2016 | JS A1008854 | Candace Burrus |
| N-7 | 11 McCarty Avenue, Richwood | 38.217501, -80.521148 | window caulking | 104LF | 3% | 12/21/2016 | JS A1008854 | Taylor B Metcalf |
| | | | caulking roof vent | 6LF | Assumed | | | |
| N-9 | 24 Brierwood (Greenbrier) Rd, Richwood | 38.221955, -80.534101 | mastic on chimney | 12LF | Assumed | 12/21/2016 | JS A1008854 | Ryan Williams |
| | | | Building b2 roof shingles | 55F | Assumed | | | |
| | | | Nats roof shingle | 10SF | Assumed | | | |
| | | | dog house shingle roof | 10SF | Assumed | | | |
| N-13 | 87 Green Street, Richwood | 38.220802, -80.551017 | Beige linoleum | 150sf | 2% | 12/21/2016 | JS A1008854 | Taylor B Metcalf |
| | | | Beige linoleum | 150sf | 25% | 12/21/2016 | JS A1008854 | Taylor B Metcalf |
| | | | Mastic on roof vents | 6LF | Assumed | 12/21/2016 | JS A1008854 | Taylor B Metcalf |

WEST VIRGINIA



R E C E I V E D
JUN 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:Original ☒Revision ☒ (Highlight Changes)Cancellation ☐**Type of Operation:**Demolition ☒ Ordered Demolition ☐Renovation ☐Emergency Renovation ☐**Facility Owner:**

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 3 (Nicholas County)

Address: _____

City: _____

County: _____

Location Within Facility: _____

Building Size (Sq. Ft.): _____

Number of Floors: _____

Age (Yrs): _____

Present Use: _____

Prior Use: _____

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: See attached

Lab: CEI Labs

WV License #: See attached

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor: _____

WV License #: _____

Schedule:

Asbestos Removal:

Start Date: 04/24/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 04/24/17


Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

W A S H I N G T O N
S T A T E

OFFICE OF THE ATTORNEY GENERAL
JANUARY 1968



Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Phone: 304-366-7070

Zip Code: 26555

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032

State: WV

Phone: 304-842-2784

Zip Code: 26330

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



RECLAIM

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Nicholas County, WV - Group 3

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTILE | INSPECTION DATE | INSPECTOR | ANALYST |
|-------|----------------------------|-----------------------|-----------------------------|--------------|-----------|-----------------|---------------------|---------------|
| N-45 | 24963 Turnpike Rd., Belva | 38.22915, -81.19275 | Silver Roof Paint | 800 SF | 3% | 12/22/2016 | J. Frazier AI008690 | Scott Minyard |
| | | | Black Tar around Roof Vents | 5 SF | Assumed | | | |
| N-105 | 24939 Turnpike Road, Belva | 38.229625, -81.192932 | Old Wiring (back of pile) | UK | Assumed | 4/22/2017 | J. Frazier AI008690 | N/A |

WEST VIRGINIA



R E C E I V E D
JUN 05 2017

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Pesticides & Asbestos Programs
and Enforcement Branch (35002)
EPA Region III

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:
Postmark Date:
Notification No:

Check No:
Paid By:
Amount: \$

Type of Notification:

Original ☐ **Revision** ☒ (Highlight Changes) Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐ Renovation ☐ Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security
Address: 1900 Kanawha Blvd., E, EB80
City: Charleston State: WV Zip Code: 25305
Contact Person: John Hoyer Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 4 (Nicholas County)
Address: City:
County: Location Within Facility:
Building Size (Sq. Ft.): Number of Floors: Age (Yrs):
Present Use: Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC Asbestos Contractor License #: AC002453
Address: P.O. Box 2162
City: Fairmont State: WV Zip Code: 26555
Contact Person: Steve Gabbert Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC Contractor's License #: WV042918
Address: P.O. Box 2162
City: Fairmont State: WV Zip Code: 26555
Contact Person: Steve Gabbert Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.
Asbestos Inspection By: See attached WV License #: See attached
Lab: CEI Labs Analysis By: Please see attached.
Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy
Is Asbestos Present at 1% or Greater: Yes ☒ No ☐
Project Designer: Chris Ciappina WV License #: AD003839
Air Monitor: WV License #:

Schedule:

Asbestos Removal: Start Date: 02/24/2017 Completion Date: 08/04/2017
Demo/Renovation: Start Date: 02/24/2017 Completion Date: 08/04/2017
Project Work Hours: 7am to 5:30pm Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

RECEIVED
JUN 10 1964

RECEIVED
JUN 10 1964
JUN 10 1964

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV


Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



RECLAIM

WVHSEM / FEMA

June 23rd Flood Cleanup Project

Nicholas County, WV - Group 4

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTOTILE | INSPECTION DATE | INSPECTOR | ANALYST | COMPLETE |
|------|------------------------------------|-----------------------|----------------------------------|--------------|-------------|-----------------|---------------------|----------------|----------|
| N-57 | 8362 WILDERNESS HWY., NALLEN | 38.113585, -80.878225 | Silver Paint | 800 SF | 2% | 2/16/2017 | J. Frazier AI008690 | Shilpa Ladekar | |
| | | | Vent Mastic on Roof | 5 LF | Assumed | | | | |
| N-44 | 8308 WILDERNESS HWY., NALLEN | 38.11425, -80.87885 | Floor Tile (bath) | 30 SF | Assumed | 2/15/2017 | J. Frazier AI008690 | Megan Rumble | |
| N-35 | 8502 WILDERNESS HWY., NALLEN | 38.112146, -80.876949 | White/Grey Transite | 1200 SF | 15% | 2/17/2017 | J. Frazier AI008690 | Shilpa Ladekar | |
| N-33 | 8300 WILDERNESS HWY., NALLEN | 38.114356, -80.879137 | Roof Vent Mastic around vents | 5 LF | Assumed | 3/21/2017 | J. Frazier AI008690 | Candace Burrus | |
| N-17 | 17 LOWER ANGLINS CREEK RD., NALLEN | 38.112249, -80.876523 | Cream/Gray Linoleum | 216 SF | 25% | 2/16/2017 | J. Frazier AI008690 | Shilpa Ladekar | |
| | | | Linoleum (RM 2-bottom) | 88 SF | Assumed | | | | |
| N-34 | 8496 Wilderness Hwy, Nallen | 38.112355, -80.877179 | Gray/White Transite Siding | 780 SF | 15% | 4/12/2017 | J. Frazier AI008690 | Megan Rumble | |
| | | | Old Roofing Material (Dog House) | 10 SF | Assumed | | | | |

WEST VIRGINIA



R E C E I V E D
JUN 05 2017

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

West Virginia Asbestos Programs
and Enforcement Branch (SLC62)
OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☐

Revision ☒ (Highlight Changes)

Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐

Renovation ☐

Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 5 (Nicholas County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: See attached

Lab: CEI Labs

WV License #: See attached

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 02/21/2017

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 02/21/2017

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

RECEIVED
JUN 20 1961

U.S. DEPARTMENT OF AGRICULTURE
WASHINGTON, D.C. 20250

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Title:

Date of Order: ___/___/___

Date Order to Begin: ___/___/___

(Copy of order must be attached.)

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



RECLAIM3

WVHSEM / FEMA

June 23rd Flood Cleanup Project

Nicholas County, WV - Group 5

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSOTILE | INSPECTION DATE | INSPECTOR | ANALYST | COMPLETE |
|------|--------------------------------|-----------------------|---|--------------|------------|-----------------|---------------------|-------------------|----------|
| N-49 | 86 Main St., Richwood | 38.22098, -80.56047 | Yellow/Brown Linoleum (Main) | 30 SF | 25% | 2/8/2017 | J. Frazier AI008690 | Anna Malmberg | X |
| | | | Tan Mastic under linoleum (Main) | 30 SF | 2% | | | | X |
| | | | Silver Roof Paint (Bldg 1) | 130 SF | 2% | | | | |
| | | | Mastic on Vent Pipe (Main) | 5 F | Assumed | | | | X |
| N-19 | 26 Birch St., Richwood | 38.216319, -80.556676 | Gray Floor Tile | 200 SF | 10% | 2/13/2017 | J. Frazier AI008690 | Greg Ruff | X |
| | | | Gray Transite | 2000 SF | 20% | | | | X |
| | | | Linoleum | 150 SF | Assumed | | | | X |
| | | | 9"x9" Floor Tile | 100 SF | Assumed | | | | X |
| N-47 | 61 Little Laurel Rd., Richwood | 38.21175, -80.55526 | Linoleum (Bldg 3) | 100 SF | Assumed | 2/13/2017 | J. Frazier AI008690 | Samantha Card | X |
| N-48 | 45 W. Main St., Richwood | 38.224374, -80.535729 | No Suspect Materials | N/A | N/A | 2/13/2017 | J. Frazier AI008690 | N/A | X |
| N-46 | 44 Commercial Ave., Richwood | 38.22248, -80.53364 | Blue Linoleum | 30 SF | Assumed | 2/13/2017 | J. Frazier AI008690 | Ryan Williams | X |
| N-56 | 63 W. Main St., Richwood | 38.223895, -80.537133 | Beige Floor Tile | 120 SF | 3% | 2/9/2017 | J. Frazier AI008690 | Samantha Card | X |
| | | | Red Tile | 80 SF | 2% | | | | X |
| | | | White/Green Linoleum | 72 SF | 25% | | | | X |
| | | | White Mud (on plaster) | 500 SF | 2% | | | | X |
| | | | 9"x9" Floor Tile | 415 SF | Assumed | | | | X |
| N-83 | 47 W. Main St., Richwood | 38.224352, -80.535905 | White/Gray Transite Siding (throughout) | UK | 15% | 2/13/2017 | J. Frazier AI008690 | Ryan Williams | |
| N-86 | 16 W. Walnut St., Richwood | 38.225094, -80.534741 | Linoleum | 30 SF | Assumed | 2/9/2017 | J. Frazier AI008690 | Mikaela Batta | X |
| N-65 | 12 W. Cranberry St., Richwood | 38.225481, -80.535402 | Old Wiring | 10 LF | Assumed | 2/8/2017 | J. Frazier AI008690 | Sarah Talley | X |
| N-64 | 8 W. Cranberry St., Richwood | 38.225766, -80.534640 | Old Wiring | 20 LF | Assumed | 2/8/2017 | J. Frazier AI008690 | Mikaela Batta | X |
| N-63 | 6 W. Cranberry St., Richwood | 38.225841, -80.534428 | Transite Siding (throughout) | UK | 15% | 2/9/2017 | J. Frazier AI008690 | Mikaela Batta | |
| N-53 | 3 W. Cranberry St., Richwood | 38.226063, -80.534623 | Old Wiring | 25 LF | Assumed | 2/9/2017 | J. Frazier AI008690 | Mikaela Batta | |
| N-52 | 1 Oak St., Richwood | 38.227182, -80.535148 | Window Glazing | 24 LF | Assumed | 2/8/2017 | J. Frazier AI008690 | Sarah Talley | X |
| | | | Off-White Window Glazing | 350 LF | 3% | 2/18/2017 | J. Frazier AI008690 | Scott Minyard | X |
| | | | Linoleum (top of stairs) | 20 SF | Assumed | | | | X |
| | | | Off-White Window Glazing (Bldg 1) | 24 LF | 3% | | | | X |
| N-68 | 7 E. Cranberry St., Richwood | 38.226508, -80.533343 | Transite Siding (mixed throughout) | UK | 15% | 2/8/2017 | J. Frazier AI008690 | Ritika Seal | |
| N-69 | 9 E. Cranberry St., Richwood | 38.226527, -80.533217 | Black Tar on Pipe | 2 SF | Assumed | 2/8/2017 | J. Frazier AI008690 | Ritika Seal | X |
| N-70 | 26 E. Cranberry St., Richwood | 38.226565, -80.532345 | Linoleum | 5 SF | Assumed | 2/8/2017 | J. Frazier AI008690 | Ritika Seal | X |
| N-71 | 28 E. Cranberry St., Richwood | 38.226598, -80.532198 | Green Linoleum | 10 SF | Assumed | 2/8/2017 | J. Frazier AI008690 | Mikaela Batta | X |
| N-72 | 36 E. Cranberry St., Richwood | 38.226708, -80.531922 | Blue & Red Linoleum | 20 SF | Assumed | 2/8/2017 | J. Frazier AI008690 | Taylor B. Metcalf | X |
| | | | Gray Transite (throughout) | UK | 15% | 2/18/2017 | J. Frazier AI008690 | Saithya Painkal | |
| N-73 | 38 E. Cranberry St., Richwood | 38.226823, -80.531614 | Green Linoleum (top) | 5 SF | Assumed | 2/18/2017 | J. Frazier AI008690 | Saithya Painkal | |
| N-74 | 55 E. Cranberry St., Richwood | 38.227476, -80.530590 | Blue Linoleum | 25 SF | Assumed | 2/8/2017 | J. Frazier AI008690 | Taylor B. Metcalf | X |
| | | | Gray Plaster (mixed throughout) | UK | 20% | 2/8/2017 | J. Frazier AI008690 | Taylor B. Metcalf | |
| N-84 | 63 E. Cranberry St., Richwood | 38.227723, -80.529876 | Chimney Mastic | 5 SF | Assumed | 2/8/2017 | J. Frazier AI008690 | Taylor B. Metcalf | |
| N-85 | 79 E. Cranberry St., Richwood | 38.228100, -80.529063 | Old Wiring | 20 LF | Assumed | 2/8/2017 | J. Frazier AI008690 | Ritika Seal | |
| N-80 | 42 W. Walnut St., Richwood | 38.224681, -80.535899 | Linoleum | 10 SF | Assumed | 2/8/2017 | J. Frazier AI008690 | Ryan Williams | X |
| N-81 | 46 W. Walnut St. Richwood | 38.224614, -80.536066 | Old Wiring | 30 LF | Assumed | 2/13/2017 | J. Frazier AI008690 | Ryan Williams | X |
| N-55 | 55 E. Walnut St., Richwood | 38.227306, -80.529636 | Old Wiring | 40 LF | Assumed | 2/13/2017 | J. Frazier AI008690 | Ryan Williams | X |
| N-82 | 65 E. Wlanut St., Richwood | 38.227500, -80.528773 | Window Glazing | 16 LF | Assumed | 2/13/2017 | J. Frazier AI008690 | Candace Burrus | X |
| N-76 | 37 Spruce St., Richwood | 38.230674, -80.527147 | Chimney Mastic | 10 LF | Assumed | 2/13/2017 | J. Frazier AI008690 | Megan Rumble | X |
| N-75 | 45 Spruce St., Richwood | 38.231163, -80.527413 | Old Wiring | 20 LF | Assumed | 2/13/2017 | J. Frazier AI008690 | Greg Ruff | X |
| | | | Gray Transite Siding (Throughout) | UK | 15% | 2/13/2017 | J. Frazier AI008690 | Taylor Metcalf | |
| N-77 | 205 Johnstown Rd., Richwood | 38.227697, -80.522205 | Old Wiring | 30 LF | Assumed | 2/13/2017 | J. Frazier AI008690 | Taylor Metcalf | |
| | | | Old Wiring | 10 LF | Assumed | 2/13/2017 | J. Frazier AI008690 | Ryan Williams | X |

| | | | | | | | | | |
|-------|---|-----------------------|-------------------------------------|---------|---------|-----------|---------------------|-------------------|---|
| N-78 | 218 Johnstown Rd., Richwood | 38.221928, -80.519834 | Window Glazing (throughout) | UK | 2% | 2/13/2017 | J. Frazier AI008690 | Samantha Card | X |
| | | | Floor Tile | 40 SF | Assumed | | | | X |
| | | | Caulking around door frame (Bldg 1) | 16 SF | Assumed | | | | X |
| N-79 | 384 Johnstown Rd., Richwood | 38.221928, -80.519834 | Silver Paint main roof | 800 SF | 2% | 2/13/2017 | J. Frazier AI008690 | Samantha Card | |
| | | | Black Tar bottom of trailer | 10 LF | Assumed | | | | |
| N-66 | 34 Hill St., Richwood | 38.223635, -80.520641 | No Suspect Materials | N/A | N/A | 2/13/2017 | J. Frazier AI008690 | N/A | X |
| N-67 | 143 Front St., Richwood | 38.224131, -80.520981 | Gray Transite Siding (Throughout) | UK | 15% | 2/13/2017 | J. Frazier AI008690 | Saithya Painkal | |
| | | | Old Wiring | 20 LF | Assumed | | | | |
| N-37 | 123 Front St., Richwood | 38.224606, -80.523146 | Linoleum | 4 SF | Assumed | 2/9/2017 | J. Frazier AI008690 | Candace Burrus | X |
| N-24 | 69 Front St., Richwood | 38.222669, -80.526147 | Mastic on Roof Vents | 5 LF | Assumed | 2/9/2017 | J. Frazier AI008690 | Ritika Seal | X |
| | | | Linoleum | 5 SF | Assumed | | | | X |
| N-26 | 76 Front St., Richwood | 38.222563, -80.525573 | Transite Siding | 500 SF | 15% | 2/9/2017 | J. Frazier AI008690 | Candace Burrus | X |
| | | | Window Glazing | 50 LF | Assumed | | | | X |
| N-58 | 12A Dyer Ave., Richwood | 38.223093, -80.526563 | None Detected | N/A | N/A | 2/9/2017 | J. Frazier AI008690 | Samantha Card | X |
| N-62 | 11 Dyer Ave., Richwood | 38.223118, -80.526977 | Linoleum | 20 SF | Assumed | 2/13/2017 | J. Frazier AI008690 | Saithya Painkal | X |
| N-61 | 6 Dyer Ave., Richwood | 38.222589, -80.527281 | Black Tar on Roof Vent | 5 LF | Assumed | 2/13/2017 | J. Frazier AI008690 | Megan Fisher | X |
| N-54 | 5 Home St., Richwood | 38.223473, -80.531601 | Linoleum | 10 SF | Assumed | 2/13/2017 | J. Frazier AI008690 | Ryan Williams | X |
| N-51 | 46 BFG St., Richwood | 38.222806, -80.533858 | Transite Siding | 1320 SF | 15% | 2/9/2017 | J. Frazier AI008690 | Shilpa Ladekar | X |
| | | | Brown Linoleum | 140 SF | 25% | | | | X |
| | | | 9"x9" Floor Tile | 140 SF | Assumed | | | | X |
| N-88 | 57 W. Main Street, Richwood (Debris Pile) | 38.224093, -80.536583 | Gray Transite (throughout) | UK | 15% | 3/21/2017 | J. Frazier AI008690 | Candace Burrus | |
| N-40 | 5 Dyer Ave., Richwood | 38.223453, -80.531890 | Old Wiring (throughout) | UK | Assumed | 3/21/2017 | J. Frazier AI008690 | Ryan Williams | |
| | | | 9"x9" Floor Tile (stacked) | UK | Assumed | | | | |
| N-36 | 0 North Fork Cherry Road, Richwood | 38.235251, -80.528733 | Gray Transite | 500 SF | 15% | 3/21/2017 | J. Frazier AI008690 | Ryan Williams | |
| | | | Gray Floor Tile/Mastic | 100 SF | 5% | | | | |
| | | | Tan/Beige Floor Tile/Mastic | 100 SF | 3% | | | | |
| | | | Linoleum | 5 SF | Assumed | | | | |
| N-50 | 432 Arlington Lane, Fenwick (Debris Pile) | 38.22451, -80.58037 | Old Wire (backside of pile) | 10 LF | Assumed | 3/21/2017 | J. Frazier AI008690 | Candace Burrus | |
| N-38 | 11 Green Street, Richwood | 38.218903, -80.555863 | Gray/Tan Transite | UK | 15% | 3/29/2017 | J. Frazier AI008690 | Sarah Talley | |
| | | | Tan Floor Tile | 100 SF | 3% | | | | |
| | | | Silver/Roof Paint (Bldg 2) | UK | 10% | | | | |
| N-59 | 12C Dyer Avenue, Richwood | 38.222924, -80.526402 | Roof Mastic | UK | Assumed | 3/29/2017 | J. Frazier AI008690 | Saithya Painkal | |
| | | | Silver Paint (main roof) | 750 SF | 2% | | | | |
| N-92 | 41 W. Main Street, Richwood | 38.224485, -80.535536 | Roof Mastic (around roof vents) | 5 LF | Assumed | 3/29/2017 | J. Frazier AI008690 | Taylor B. Metcalf | |
| N-39 | 369 Johnstown Road, Richwood | 38.224168, -80.519262 | Window Glazing | 5 LF | Assumed | 4/12/2017 | J. Frazier AI008690 | Greg Ruff | |
| N-90 | 203 (6) Weber St., Richwood | 38.230177, -80.523896 | Box of 9"x9" Floor Tile in kitchen | 20 SF | Assumed | 4/12/2017 | J. Frazier AI008690 | Greg Ruff | |
| | | | Blue Floor Tile & Mastic | 20 SF | 5% | | | | |
| N-100 | 42 Lot D Riverside Dr., Richwood | 38.221225, -80.536580 | Old Wire (back left side of pile) | 25 LF | Assumed | | | | |
| N-104 | 761 Richwood Rd., Richwood | 38.219724, -80.554539 | Old Wiring (behind pile) | 50 LF | Assumed | 4/12/2017 | J. Frazier AI008690 | Samantha Card | |

WEST VIRGINIA


 RECEIVED
 JUN 05 2017

 Pesticides & Asbestos Programs
 and Enforcement Branch (304) 306-1111
 EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

| | |
|------------------|------------|
| Date Rec'd: | Check No: |
| Postmark Date: | Paid By: |
| Notification No: | Amount: \$ |

Type of Notification:
Original ☐**Revision** ☒ (Highlight Changes)Cancellation ☐
Type of Operation:
Demolition ☒ Ordered Demolition ☐Renovation ☐Emergency Renovation ☐
Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 6 (Nicholas County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002330

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: See attached

Lab: CEI Labs

WV License #: See attached

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 02/24/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 02/24/17

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Q V I S S E
Q

THE ABOVE INFORMATION IS
FOR THE USE OF THE
OFFICE ONLY

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



RECLAIM

WVHSEM / FEMA

June 23rd Flood Cleanup Project

Nicholas County, WV - Group 6

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTILE | INSPECTION DATE | INSPECTOR | ANALYST | COMPLETE |
|------|---|-----------------------|-----------------------------------|--------------|-----------|-----------------|---------------------|-----------------|----------|
| N-32 | 457 FIRE TOWER RD., CRAIGSVILLE | 38.351257, -80.632543 | Vent Mastic (roof) | 5 LF | Assumed | 2/15/2017 | J. Frazier AI008690 | Scott Minyard | |
| N-29 | 104 BUNKER ST., BIRCH RIVER | 38.499587, 80.752548 | Silver Paint (mixed throughout) | UK | 3% | 2/15/2017 | J. Frazier AI008690 | Mikaela Batta | |
| | | | 9"x9" Floor Tile | 10 SF | Assumed | | | | |
| N-31 | 155 POWELL CREEK RD., BIRCH RIVER | 38.496794, -80.756042 | Green/White Window Glazing | 200 LF | 2% | 2/15/2017 | J. Frazier AI008690 | Samantha Card | |
| | | | Linoleum (kitchen) | 140 SF | Assumed | | | | |
| N-41 | 159 Bunker St., Birch River (Debris Pile) | 38.500045, -80.753312 | Silver Paint on Metal Roofing | UK | 2% | 3/21/2017 | J. Frazier AI008690 | Candace Burrus | |
| | | | Linoleum (left side) | 5 SF | Assumed | | | | |
| N-23 | 56 POWELL CREEK RD., BIRCH RIVER | 38.498296, -80.755839 | Vent Mastic (3 roof vents) | 3 LF | Assumed | 2/15/2017 | J. Frazier AI008690 | Samantha Card | |
| N-21 | 40 POWELL CREEK RD., BIRCH RIVER | 38.498579, -80.755678 | Floor Tile | 30 SF | Assumed | 2/17/2017 | J. Frazier AI008690 | Mikaela Batta | |
| N-28 | 83 BUNKER ST., BIRCH RIVER | 38.499369, -80.753053 | Linoleum (bath) | 30 SF | Assumed | 2/15/2017 | J. Frazier AI008690 | Megan Rumble | |
| N-25 | 71 BUNKER STREET, BIRCH RIVER | 38.499211, -80.753198 | 12"x12" Floor Tile (BR 1/Hallway) | 20 SF | Assumed | 3/29/2017 | J. Frazier AI008690 | Saithya Painkal | |

WEST VIRGINIA



R E C E I V E D
JUN 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☒

Revision ☐ (Highlight Changes)

Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐

Renovation ☐

Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 1 (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

Lab: CEI Labs

WV License #: AI008690

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 05/31/17

Completion Date: 08/04/2017

Demo/Renovation:

Start Date: 05/31/17

Completion Date: 08/04/2017

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

0 9 7 1 3 0 3 0
100 00 000

100 00 000
100 00 000
100 00 000

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Title:

Date of Order: ___/___/___

Date Order to Begin: ___/___/___

(Copy of order must be attached.)

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator:

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina Environmental Program Manager



RECLAIM3

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 1

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTILE | INSPECTION DATE | ANALYST | COMPLETE |
|-------|--|-----------------------|------------------------|--------------|-----------|-----------------|-------------------|----------|
| K-126 | 56 Harlech Lane, Elkview | 38.40892, -81.51071 | Linoleum | 20 SF | Assumed | 12/12/2016 | Sarah Talley | X |
| K-2 | 40 Benthaven Lane, Elkview | 38.428593, -81.515804 | Window Glazing | 32 LF | 3% | 11/17/2016 | Anna Malmberg | X |
| K-47 | 416 Briarwood Road, Elkview | 38.2543, -81.3026 | Silver Paint | 600 SF | 2% | 11/17/2016 | Megan Fisher | X |
| K-48 | 430 Briarwood Road, Elkview | 38.42838, -81.50705 | None Detected | N/A | N/A | 11/17/2016 | Mikaela Batta | X |
| K-49 | 416 A Briarwood Road, Elkview | 38.42859, -81.50787 | Black/Silver Tar | 638 SF | 5% | 11/17/2016 | Anna Malmberg | X |
| | | | Silver Paint | 638 SF | 5% | 11/17/2016 | | |
| | | | Black/Silver Paint | 638 SF | 2% | 11/17/2016 | | |
| K-77 | 381 West Wood Drive, Elkview | 38.41741, -81.504187 | None Detected | N/A | N/A | 11/17/2016 | Megan Fisher | X |
| K-87 | 561-B Little Sandy Creek Road, Elkview | 38.41842, -81.50396 | Linoleum | 30 SF | Assumed | 11/21/2016 | Taylor B. Metcalf | |
| K-55 | 3279 Frame Road, Elkview | 38.46861, -81.499383 | Silver/Black Caulking | 10 LF | 5% | 11/17/2016 | Anna Malmberg | X |
| K-55 | 3279 Frame Road, Elkview | 38.46861, -81.499383 | Bldg 1 - Roof Mastic | 30 LF | 3% | 1/17/2017 | Saithya Painkal | |
| K-56 | 3319 Frame Road, Elkview | 38.469, -81.49932 | Silver Paint on Roof | 1260 SF | Assumed | 11/18/2016 | Taylor B. Metcalf | X |
| K-5 | 1788 Wills Creek Road, Elkview | 38.2791, -81.29185 | Black Tar on shingles | 1280 SF | Assumed | 11/19/2016 | Mikaela Batta | X |
| K-4 | 29 Little Fork Road, Elkview | 38.485903, -81.455825 | Transite Siding | 1900 SF | Assumed | 11/18/2016 | Samantha Card | X |
| K-6 | 5945 Wills Creek Road, Elkview | 38.4884, -81.42901 | Transite Siding | 1200 SF | Assumed | 11/18/2016 | Samantha Card | X |
| | | | Black Tar | 1500 SF | 5% | 11/18/2016 | | |
| | | | Black Tar | 1500 SF | 5% | 11/18/2016 | | |
| | | | Window Glazing | 70 LF | 5% | 11/18/2016 | | |
| | | | Window Glazing | 70 LF | 5% | 11/18/2016 | | |
| K-127 | 3091 Frame Road, Elkview | 38.46586, -81.49936 | Black Tar - Roof Vents | 20 SF | Assumed | 12/12/2016 | Daniel Liguori | |
| K-115 | 7369 Wills Creek Road, Elkview | 38.50279, -81.41266 | Linoleum in Bathroom | 25 SF | Assumed | 12/16/2016 | Taylor B. Metcalf | X |

WEST VIRGINIA



RECEIVED
JUN 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (SLC62)
EPA Reg.

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☒

Revision ☐ (Highlight Changes)

Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐

Renovation ☐

Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 4 (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

Lab: CEI Labs

WV License #: AI008690

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 05/31/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 05/31/17

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Page 7
of 8

1986-87

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

| | | |
|--------|---------|-------------|
| Pipes: | Ln. Ft: | % Asbestos: |
| Area: | Sq. Ft: | % Asbestos: |
| Other: | Cu. Ft: | % Asbestos: |

Type(s):

| | | |
|--------|---------|-------------|
| Pipes: | Ln. Ft: | % Asbestos: |
| Area: | Sq. Ft: | % Asbestos: |
| Other: | Cu. Ft: | % Asbestos: |

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Zip Code: 26555

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032

State: WV

Zip Code: 26330

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 4

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTOLE | INSPECTION DATE | ANALYST | COMPLETE |
|------|------------------------------------|---------------------|-----------------------------|----------------|-----------|-----------------|-----------------|----------|
| K-53 | 5538 Elk River Road, Elkview | 38.46992, -81.4005 | Linoleum | 5 SF | Assumed | 12/2/2016 | Shilpa Ladekar | X |
| K-18 | 1444 Jordan Creek Road, Elkview | 38.47775, -81.39781 | Silver Paint | 600 SF | 2% | 12/2/2016 | Shilpa Ladekar | X |
| | | | Linoleum | 100 SF | Assumed | | | |
| K-3 | 2007 Jordan Creek Road, Elkview | 38.48288, -81.38996 | Silver Paint on Roof | 600 SF | Assumed | 12/2/2016 | Shilpa Ladekar | |
| | | | Linoleum | UK (no access) | Assumed | | | |
| K-65 | 31 Strawberry Path Lane, Clendenin | 38.4729, -81.39635 | Window Glazing | 64 LF | 2% | 12/2/2016 | Salthya Painkal | X |
| | | | Floor Tile | 2 SF | Assumed | | | |
| K-66 | 61 Strawberry Path Lane, Clendenin | 38.2821, -81.2350 | Black Tar (back porch roof) | 5 LF | Assumed | 12/2/2016 | Candace Burrus | X |
| K-45 | 102 Wall Street, Clendenin | 38.28958, -81.21892 | Linoleum | 170 SF | 25% | 12/5/2016 | Shilpa Ladekar | X |
| | | | Floor Tile | 144 SF | 25% | | | |
| | | | Black Tar | 2 LF | Assumed | | | |
| K-89 | 5 Chandler Lane, Clendenin | 38.48024, -81.36804 | Linoleum | 45 SF | Assumed | 12/14/2016 | Shilpa Ladekar | |
| K-19 | 120 Kelly Avenue, Clendenin | 38.4816, -81.365158 | Black Tar on roof vent | 3 SF | Assumed | 12/5/2016 | Shilpa Ladekar | X |
| K-17 | 301 S. Elk River Road, Clendenin | 38.48411, -81.36026 | Black Tar | 4 LF | Assumed | 12/2/2016 | Sarah Talley | X |
| K-16 | 47 S. Elk River Road, Clendenin | 38.48457, -81.35962 | Brown Floor Tile | 900 SF | 5% | 12/5/2016 | Sarah Talley | X |
| | | | White Floor Tile | 900 SF | 2% | | | |
| | | | Window Caulking | 144 LF | 5% | | | |
| | | | Window Glazing | 20 LF | Assumed | | | |
| K-15 | 27 S. Elk River Road, Clendenin | 38.52611, -81.47361 | Pipe Wrap | 60 LF | Assumed | 12/5/2016 | Salthya Painkal | X |
| | | | Exterior Caulking on gutter | 6 LF | Assumed | | | |

WEST VIRGINIA



RECEIVED
JUN 05 2017

Pesticides & Asbestos Programs
and Enforcement Branch (SLC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☒Revision ☒ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 6 (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

Lab: CEI Labs

WV License #: AI008690

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 05/01/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 05/01/17

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Q E W I F 3 E Q
Q W K P G M L Q

Position: Assistant Professor
Department: Biology
Institution: University of California, San Diego

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV


Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina/Environmental Program Manager



RECLAIM

WVHSEM / FEMA

June 23rd Flood Cleanup Project

Kanawha County, WV - Group 6

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTILE | INSPECTOR | INSPECTION DATE | ANALYST | COMPLETE |
|------|-------------------------------|----------------------|-------------------------|--------------|-----------|---------------------|-----------------|---------------|----------|
| K-25 | 306 Maywood Drive, Clendenin | 38.48730, -81.35205 | Mastic around roof vent | 4 LF | Assumed | J. Sommers AI008854 | 12/7/2016 | Anna Malmberg | X |
| K-24 | 110 Maywood Avenue, Clendenin | 38.48825, -81.34988 | Linoleum | 12 SF | Assumed | J. Sommers AI008854 | 12/7/2016 | Anna Malmberg | X |
| K-20 | 214 Koontz Avenue, Clendenin | 38.489924, -81.34357 | Wiring in house | 100 LF | Assumed | J. Sommers AI008854 | 12/7/2016 | Scott Minyard | X |
| K-14 | 202 Elk Avenue, Elkview | 38.48844, -81.35105 | Roof vent mastic | 12 LF | Assumed | J. Frazier AI008690 | 4/20/2017 | Mikaela Batta | X |
| K-27 | 5 Pleasant Street, Clendenin | 38.48784, -81.35135 | Mastic around roof vent | 5 LF | Assumed | J. Sommers AI008854 | 12/7/2016 | Anna Malmberg | X |
| K-80 | 110 Koontz Avenue, Clendenin | | Transite Siding | 800 SF | 15% | J. Frazier AI008690 | 12/13/2016 | Sarah Talley | X |
| | | | Floor Tile | 150 SF | Assumed | | | | |

WEST VIRGINIA


 RECEIVED
JUN 05 2017

 Pesticides & Asbestos Programs
and Enforcement Branch (StC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

| | |
|------------------|------------|
| Date Rec'd: | Check No: |
| Postmark Date: | Paid By: |
| Notification No: | Amount: \$ |

Type of Notification:

Original ☒Revision ☐ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 10 (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

WV License #: AI008690

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 05/31/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 05/31/17

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

to the ...
...
...

...

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV


Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Ciappina Environmental Program Manager



RECLAIM

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 10

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTOLE | INSPECTOR | INSPECTION DATE | ANALYST | COMPLETE |
|-------|------------------------------|-----------------------|--------------------------|--------------|-----------|---------------------|-----------------|-------------------|----------|
| K-145 | 766 Islandview Road, Elkview | 38.442844, -81.466197 | Mastic on Roof Vent | 5 SF | Assumed | J. Frazier AI008690 | 2/1/2017 | Candace Burrus | X |
| K-113 | 32 Skunk Dr., Elkview | 38.45021, -81.45723 | Roof Mastic around vents | 5 LF | Assumed | J. Frazier AI008690 | 3/27/2017 | Megan Fisher | |
| K-148 | 132 3rd Ave., Elkview | 38.443006, -81.469175 | None Detected | N/A | N/A | J. Frazier AI008690 | 3/27/2017 | Taylor B. Metcalf | |

WEST VIRGINIA



RECEIVED
JUN 05 2017

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Pesticides & Asbestos Programs
Renovation (3LC62)

EPA Region III

Date: 5/31/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: Check No:

Postmark Date: Paid By:

Notification No: Amount: \$

Type of Notification:

Original ☐

Revision ☒ (Highlight Changes)

Cancellation ☐

Type of Operation:

Demolition ☒ Ordered Demolition ☐

Renovation ☐

Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 14 (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002453

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

Lab: CEI Labs

WV License #: AI008690

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Chris Ciappina

WV License #: AD003839

Air Monitor:

WV License #:

Schedule:

Asbestos Removal:

Start Date: 03/06/17

Completion Date: 08/04/17

Demo/Renovation:

Start Date: 03/06/17

Completion Date: 08/04/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

SECRET
JUN 10 1961

Approved for Release by NSA
on 08-28-2013 pursuant to E.O. 13526

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Title:

Date of Order: ___/___/___

Date Order to Begin: ___/___/___

(Copy of order must be attached.)

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 05 / 31 / 17

Name and Title (Print or Type): Christopher Cioppina/ Environmental Program Manager



RECLAIM

WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 14

| SITE | ADDRESS | GPS | ASBESTOS TO BE REMOVED | APPROX. SIZE | CHRYSTILE | INSPECTOR | INSPECTION DATE | ANALYST | COMPLETE |
|-------|-------------------------------------|-----------------------|-------------------------|--------------|-----------|---------------------|-----------------|----------------|----------|
| K-92 | 4 Elk Ave., Clendenin | 38.48946, -81.34846 | 9"x9" Floor Tile | 120 SF | Assumed | J. Frazier AI008690 | 2/7/2017 | Megan Fisher | |
| K-93 | 202-1/2 Koontz Ave., Clendenin | 38.48972, -81.34458 | Window Glazing | 80 LF | Assumed | J. Frazier AI008690 | 2/2/2017 | Candace Burrus | |
| K-96 | 966 Spencer Rd., Clendenin | 38.49522, -81.35238 | Window Glazing | 10 LF | Assumed | J. Frazier AI008690 | 2/2/2017 | Shilpa Ladekar | |
| K-97 | 200 Thorofare Road, Clendenin | 38.50063, -81.34624 | Roof Mastic around vent | 4 SF | Assumed | J. Frazier AI008690 | 4/11/2017 | Shilpa Ladekar | |
| K-189 | 3950 Thorofare Road, Clendenin | 38.524307, -81.317491 | Linoleum (Bath) | 20 SF | Assumed | J. Frazier AI008690 | 4/11/2017 | Greg Ruff | |
| K-190 | 4 Little Blue Creed Road, Clendenin | 38.524147, -81.302175 | Linoleum (hallway) | 10 SF | Assumed | J. Frazier AI008690 | 4/11/2017 | Ritika Seal | |

RECLAIM

62 • FAIRMONT, WV 26555



1000



19103

U.S. POSTAGE
PAID
FAIRMONT, WV
26554
MAY 31, 17
AMOUNT

\$3.29

R2305K143142-05

FIRST CLASS

Attention: Asbestos Coordinator(3WC32)
U.S. Environmental Protection Agency
Region III
1650 Arch Street
Philadelphia, PA 19103-2029

